

Geochron Refurbishment Program

After 6-7 years or so your Geochron may benefit from a refurbishment. The two main determinates of this need are, how many hours a day the lights of the unit are on and if the unit is mounted in a somewhat dusty environment.

The first thing to do if you would like to have the factory work on your Geochron is to check the age of the unit. You can tell the age of your piece by looking at the first 4 digits of the unit's serial number. These are located on the back bottom of the Geochron in the middle (insert photo). The first 4 digits represent the "year and month" the Geochron was "manufactured". For example a serial number 9702-34567 was produced in the in 1997 and in the month of February.

The second thing is to see if you have the original packaging that the unit came in. The Geochron is a precision handmade instrument that has packaging that is designed, tested and insured, to keep your unit safe during transport. If you do not have the original packaging, you will need to call us. We will sell you the required packaging for \$39.95 (plus shipping). **Please note: If you have a Boardroom Model we will need to know this so that so we can ship you the slightly larger carton system**

Sorry but we will not accept units back for refurbishment that are not shipped using these factory approved material without prior approval.

The prices below are based on over 30 + years of service experience. Occasionally a unit will come into the factory with freight damage or a preexisting condition that does not allow us to stay within these quoted prices, but those cases are rare and obvious. If this event does occur we will contact you with a specific price for the additional repairs and we will not proceed until you have authorized the additional costs. *The prices below are the costs for complete refurbishments of units and do not include shipping.* Our experience indicates that repairing some parts of the Geochron while leaving the cleaning and an overall refurbishment for later, leads to unsatisfactory results. Since a large portion of the costs are related to opening, closing, cleaning and calibrating each unit anyway, we will only do "repair only" in rare circumstances.

The standard refurbishment typically takes 3 to 4 weeks to complete and includes new motors (for all units over 7 years old) a new map, map guide lines, new lighting components, a new diffuser and shading and reed sleeve assembly, as well as a complete and thorough cleaning, lubrication and recalibration of your unit. The repaired unit carries a 180 day limited warranty starting on the day we ship your Geochron back to you.

The payment information you provide on the RMA form will only be charged when the work is completed and is ready to ship back to you. The unit will ship UPS Ground with insurance and these charges will be added to the prices below to arrive at your total charge. Any units whose bill remains unpaid after 60 days of completion, will become property of Geochron.

Year Mfg	UL Listed	Price Quote
1965-1976	No	Requires quote
1977-1985	Yes	\$700
1986-1996	Yes	\$625
1997-2003	Yes	\$550
2004-2007	Yes	\$400

Thank you for the opportunity to work on your Geochron and we look forward to helping you have many more years of enjoyable use with the ultimate time keeping device !

Ship to address:

Geochron, Inc.
11924 NE Sumner St
Portland, OR 97220

Ph # 1-800-342-1661